Karnataka Fire and Emergency Services Department



Office of the Chief fire officer,
Bangalore west zone, High-ground fire station premises,
Sheshadri road, Bangalore – 560 009.
080 – 22971523 / 500 / 600. Fax: 080 – 22971523.



No.109/CFO/BWZ/2022

14-02-2022

To,

The Authorized Signatory, Podar International School, Sy. No. 85, Chikka Kodigehalli, Off Magadi Road, Yeshwahtpura Hobli, Bengaluru 560 091.

Sir,

Sub: Issue of 'Fire safety Recommendation' to Podar International School Sy. No. 85, Chikka Kodigehalli, Off Magadi Road, Yeshwanthpura Hobli, Bengaluru.

Ref: Your letter Dated 05-02-2022.

*** ***

With reference to the subject above cited, the premises of *Podar International School*, situated at *Sy. No. 85, Chikka Kodigehalli, Off Magadi Road, Yeshwanthpura Hobli, Bengaluru* was inspected by undersigned on 11-02-2022 with respect to Fire prevention, Fire fighting and Evacuation measures to be complied in the above premises and has submitted the details as under;

ANNEXURE-B

NBC-2016, Part-4, Table 7 (11) 3.1.3 Group B Educational Buildings Sub division B1 & B2. (These condition are indicative and not exclusive all relevant provisions related to fire and life safety of NBC 2016 are mandatory.)

A. Details of the building / premises :-

01.	Name and Address of the Applicant.		The Authorized Signatory, Podar International School, Sy. No. 85, Chikka Kodigehalli, Off Magadi Road, Yeshwahtpura Hobli, Bengaluru 560 091.		



0.0	Name and Address of the	:	Podar International School,		
02.	premises.		Sy. No. 85, Chikka Kodigehalli,		
	premises.		Off Magadi Road, Yeshwahtpura Hobli,		
			Bengaluru 560 091.		
03.	. Name & address of the building		Podar International School,		
	owner		Sy. No. 85, Chikka Kodigehalli,		
			Off Magadi Road, Yeshwahtpura Hobli,		
			Bengaluru 560 091.		
04.	Number of buildings	:			
05.	umber of floors		Ground & 3 upper floors.		
06.	Floor-wise details of occupancy:-				
	Ground floor	:	7 class rooms, computer lab, medical		
			room, canteen, PT room, principal room,		
	·		head master room, conference room, staff		
			room & reception room.		
	1 st floor	:	Library, science lab, Yoga / Meditation		
			room, coordinator room, activity room &		
	2 nd floor	:	7 class rooms. 12 class rooms		
			12 Class Tooms		
	3 rd floor	:	12 class rooms		
07.			13.40 mtrs		
08.			6332.22 Sq. Mtrs		
09.	Built-up area of each floor:-				
	Ground floor	:	2921.00 Sq. mtrs		
	1 st floor	:	2921.00 Sq. mtrs		
	2 nd floor	:	2921.00 Sq. mtrs		
	3 rd floor	:	2921.00 Sq. Mtrs		
10	Tatal hadden ones	:	11684.00 Sq. Mtrs.		
10.					
11.	Surrounding properties:- East		Garden & open land		
	West	:	12.00 mtrs wide road		
	North	•	Vacant land.		
	South	:	Club & restaurant building		
			chief Fire		

Office of

-02

B. On inspection of this <u>School premises</u>, the following fire prevention, fire fighting and evacuation measures recommended are considered absolutely essential from fire safety

point of view :-

point of view:-						
Sl. No. (1)	Details (02)	Existing (03)		•	Recommendations (04)	
01.	Accessibility to the Premises	The premises is abutting from 12.00 mtrs wide road located on the western side & it is hard enough to carry the weight of water tender.				
02.	Number of entrances	One main entry of 07.60 mtrs width has been provided.		Complied.		
03.	Diesel generator	One generator of 62.50 KVA capacity has been provided & it is connected to all the staircase lighting, corridor lighting & other utilities.		Complied		
04.	Number of staircase	Nos. of staircases Width of staircases Width of treads Height of risers Nos. of riser per flight Height of handrails	: : : : : : : : : : : : : : : : : : : :	1. 01.50 mtrs 2. 01.20 mtrs 30 Cms 15 Cms 10 Nos	Complied	
05.	Portable extinguishers	07 ABC type fire extinguishers, each of 4 kgs capacity have been provided in each floor.			A. One water mist & CAFS type fire extinguisher of 9 ltrs capacity should kept near each staircase landing. B. One mechanical foam extinguisher of 9 ltrs capacity & One ABC type extinguisher of 6 kgs capacity should be provided near diesel generator.	

			One CO2 type fire extinguisher, of 4.5 kgs capacity should be provided near each electrical panel board & electrical room.
06.	Hose reel hose	Not provided	One Hose Reel Hose
	system	·	system for every 1000
			Sq. mtrs should be
			provided. Each hose reel
			hose of min 19 mm size
			and of adequate length to
		·	reach the farthest point of
			each floor should be
			provided shut off branch
			having a nozzle of 5mm
			size. The hose reel hose
			should be connected at
07.	Terrace tank	Not many 1-1	each landing.
07.	over	Not provided	The system should be
	respective		connected to an over head
	tower terrace.		tank of 10,000 ltrs
			capacity.
08.	At the terrace	Not provided	The system should be
	tank level		connected to an booster
	with minimum		pump of 450 LPM.
	pressure of		Further the system should
	3.5 kg/cm^2 .		be connected to an alternative source of power
			supply.
			Complied
09.	Escape routes	Direction in which the students have	Compile
		to move in the event of an emergency have been displayed in the corridor	,
		on each floor during evacuation.	
		On cach floor damage	
			Chief Fi
			othe Chief Fire On

	10. Fire order (Fire safety plans)	A notice board Have been indicated the action should be taken by the employees in case of any emergency have been displayed with the telephone number of Sunkadakette fire station i.e 080-22971600 & 101, 550, 500 & 600 and the telephone number of nearest ambulance service & Police station.	Complica
1	1. No smoking board	COTPA Sec-4 directing No Smoking area smoking here is an offence board should be written in English & Kannada both language has been prominently displayed at inside the entry / exit of the each floor.	Complied
12	Fire fighting training	3 employees have undergone trained in basic fire fighting at R.A. Mundkur Fire and Emergency Services Academy, Bannerughatta road, Bangalore	
13	Fire precaution	arv measures :-	

13. Fire precautionary measures:-

- A. Explosive and flammable materials should not be stored in the store room, UPS room, Electrical panel area, class rooms, laboratory & electrical sum panel premises.
- B. Accumulation of combustible waste in and around the premises should be avoided.
- C. The exit ways shall be always kept clear without any obstruction.
- D. Liquefied petroleum gas should not be stored in the building.
- E. The doors shall not be kept locked / latched during working hours and shall be free from obstruction.
- F. During the class hours the class room doors shall not be locked from inside to out side.
- G. As per Hon'ble supreme court order all teachers and staffs shall be trained to handle safety equipment, initiate emergency evacuation and protect their students in the event of fire and other emergency and the school shall observe the Fire Safety Day on April 14th of every year by conducting Fire Safety drills with co-ordinate with fire service department.

Dale Dale

Under the above circumstance the Karnataka Fire & Emergency Service Department is issuing 'Fire Safety Recommendation' to Podar International School, situated at Sy. No. 85, Chikka Kodigehalli, Off Magadi Road, Yeshwanthpura Hobli, Bengaluru subject to condition and compliance of the above recommendations in column -4 of serial – B within 3 months and compliance to the undersigned.

This 'Fire Safety Recommendation' is issued for a period of only one year from the date of issue and is renewable.

*All requirements recommended above are as per National Building Code-2016 Part-4 clause 3.1.3 of Fire and Life safety will have to be complied with mandatorily.

Yours faithfully

Chief Fire Officer
Bangalore West, Sheshadri Road,
Highground Fire Station Premises,
Bangalore - 560 009.