

कार्यकारी अगिरांता खांचे कार्यालाख उत्तर रत्नागिरी सा.बां.विभाग, रत्नागिरी ४१५ ६१२ ६(०२३५२) २२३५०५

Email:northratnagiri.ee@mahapwd.gov.in

जा.क्र./एनआरडी/डिबी/डिएम/प्रमाणपत्र/ 2370 दिनांक :- 25 MAR 2022

TO,

PODAR INTERNATIONAL SCHOOL

S.N.26 B, Ravindra Nagar,

Near Regalia Konkan, Karwanchiwadi,

Kuwarbhav, Ratnagiri-415639

विषय :- शाळेची इमारत नॅशनल बिल्डींग कोडप्रमाणे असलेचे प्रमाणपत्र मिळणेबबात..

संदर्भ :- १) आपले जावक पत्र क्र. ५४९/PIS/२०२२ दिनांक २१.०३.२०२२

२) या कार्यालयाचे जावक पत्र क्र. एनआरडी/डिबी/डिएम/प्रमाणपत्र/२९०० दि.५/०४/२०१८

उपरोक्त संदर्भित पत्र क्र.२ अन्वये आपणास इमारतीचे स्थिरता प्रमाणपत्र (नॅशनल बिल्डींग कोड) देण्यात आले होते. संदर्भिय पत्र क्र. १ अन्वये आपण शाळेची इमारत नॅशनल बिल्डींग कोडप्रमाणे असलेचे प्रमाणपत्र मिळणेबाबात पुन्हा विनंती केली आहे. त्याअनुषंगाने खालील अटींना अधीन राहून पुन्हा इमारत स्थिरता प्रमाणपत्र (स्टॅबिलिटी सर्टिफिकेट) देण्यात येत आहे.

- श) कामाचे संकल्पन निलेश गुंदेचा, रत्नागिरी यांनी केलेले आहे व नॅशनल बिल्डींग कोडच्या मानकाचे पालन केलेले आहे अशी धारणा आहे.
- २) इमारतीचे सविस्तर सलोह संकल्पन प्रकाश गुजर ॲन्ड असोसिएट्स, सातारा यांनी केलेले असून, त्यांनी श्री. विलास शंकरराव इंदलकर यांना दि. ०३/१०/२०१७ रोजी दिलेल्या प्रमाणपत्रानुसार इमारत भूकंप प्रवण क्षेत्र ४, अति पर्जन्यमान क्षेत्र, व समुद्रकिना-यापासून ५ कि.मी. अंतराच्या आतील इमारतींना लागू असलेले बांधकामाच्या मानकाप्रमाणे आर.सी.सी.बांधकाम केलेले आहे.
- ३) मुद्या क्र.२ मध्ये नमूद प्रमाणपत्रानुसार, व प्रकाश गुजर ॲन्ड असोसिएट्स, सातारा यांनी केलेल्या सलोह संकल्पनानुसार तसेच मुद्या क्र. १ मध्ये नमूद सविस्तर वास्तूशास्त्रीय संकल्पनाप्रमाणे वेदांत कन्स्ट्रक्शन, सातारा यांनी शाळेच्या इमारतीचे बांधकाम केलेले आहे. तसे प्रमाणपत्र वेदांत कन्स्ट्रक्शन, सातारा यांचे भागीदार श्री. संदीप चव्हाण यांनी दि. ०३/१०/२०१७ रोजी सादर केलेले आहे.
- ४) सलोह संकल्पन सल्लागार प्रकाश गुजर ॲन्ड असोसिएट्स, सातारा यांच्या दि.०३/१०/२०१७ च्या प्रमाणपत्रानुसार इमारतीचे देखभाल, दुरूस्ती किंवा नुतनीकरण करताना आर.सी.सी. घटकांना बाधा येणार नाही याची दक्षता भविष्यात घ्यावयाची आहे. तसेच शाळेच्या इमारतीमध्ये प्रमाणापेक्षा जास्त वजनी साहित्य साठवणूक होणार नाही याची दक्षता कटाक्षाने घ्यावी.
- ५) आपत्कालीन स्थितीमध्ये विदयार्थ्यांना त्वरीत शाळेच्या बाहेर पडता येण्यासाठी मार्गिका (पॅसेज) अडथळा विरहीत ठेवाव्यात. तसेच आपत्कालीन स्थितीत एकत्र जमण्याचा नकाशा तयार करून प्रत्येक वर्गखोलीत लावण्यात यावा.
- ६) अग्निशमनाकरिता दंडगोल बसविण्यात आल्याचे दिसून आले. त्यांची नियमितपणे तपासणी करून पुनर्भरण किंवा नवीन बसविण्यात यावेत.
- ७) इमारतीच्या कोणत्याही भागातील विशेषत: प्रसाधनगृहे, उपहारगृहे येथून होणारी पाण्याची गळती वेळच्या वेळी दुरूस्ती करून गळती विरहीत इमारत ठेवण्यात यावी.

कार्यकारी अभियंता उत्तर रत्नागिरी (सा.बां) विभाग रत्नागिरी



Office of Executive Engineer North Ratnagiri Public Works Department, Ratnagiri 415 612 & (02352) 223505 Email : <u>northratnagiri.ee@mahapwd.com</u>

Outward No./NRD/DB/DM/Certificate/2370 Date : 25 APR 2022

.....

To,

PODAR INTERNATIONAL SCHOOL

S. N. 26 B, Ravindra Nagar,

Near Regalia Konkan, Karwanchiwadi,

Kuwarbav, Ratnagiri - 415639



Subject :- Issuance of Stability Certificate as per National Building code for school.

Reference :- 1) Your Letter Outward No.549/PIS/2022 dt. 21/03/2022

2) Letter bearing No. NRD/DB/DAM/Certificate/2900, dt. 05/04/2018

As per the aforesaid letter No.02, Stability Certificate (National Building Code) of the building has been issued. As per the Letter No.01 as aforesaid you have again requested to issue Certificate of School Building as per National Building Code. Therefore, Building Stability Certificate is hereby issued as per the following terms.

- 1) Mr. Nilesh Gundecha, Ratnagiri has designed the work and it is according to the National Building Code Standard.
- 2) The detailed R.C.C design of the building is prepared by Prakash Gujar and Associates, Satara and as per the Certificate dt. 03/10/2017 issued by Mr. Vilas Shankarrao Indulkar, the R.C.C. construction work of the building is completed as per the Standard Code of construction applicable to the buildings situated at a distance of 5 k.m. from Sea Shore, Heavy Rain Fall Area, Earthquake Prone Area 4.
- 3) As per the Certificate mentioned in Point No. 2 and as per the R.C.C design prepared by Prakash Gujar and Associates, Satara and as per the architectural design mentioned in Point No. 1, Vedant Construction, Satara has completed the construction of School Building and accordingly Mr. Sandip Chavan, Partner of Vedant Construction, Satara has submitted the certificate dt. 03/10/2017.
- 4) As per the Certificate dt. 03/10/2017 issued by R.C.C. Design Consultant Prakash Gujar and Associates, Satara, it is necessary to take due care and precaution and should not cause harm to the R.C.C structure at the time of maintenance, repair and renovation of the school building. Further, it is also necessary to take precaution and the bulky stock should not be kept in the school building beyond normal limits.

- 5) It is necessary to keep passages without any obstacles to exit from the school in case of emergency. Further, it is also necessary to prepare the map to gather in case of emergency and it should be displayed in each classroom.
- 6) It was also notice that Fire Extinguishers were installed. It is necessary to check Fire Extinguishers regularly, to refill or to install new instruments.
- 7) It is necessary to repair water leakages in the building and especially in the lavatories and canteen and to maintain the building without any leakage.

Executive Engineer North Ratnagiri (Public Works) Department Ratnagiri

Note : This is translation of **Stability Certificate dt. 25/03/2022** written in Marathi Language into English Language. The above translation is verified by me and it is correct and appropriate.



Amol A. Shinde NOTARY & ADVOCATE Krishnakunj, Near Vitthal Mandir, Utkarsh Nagar, Tal/Dist. - Ratnagin Pin - 415 639 Mob: 9822687375