

**Government of Maharashtra**  
**Public works department Hingoli**

E Mail  
[hingoli.ee@mahapwd.gov.in](mailto:hingoli.ee@mahapwd.gov.in)

Office  
Executive Engineer  
PWD Hingoli

Outward No /2780

Date: 07<sup>th</sup> July 2022

To,  
Principal,  
Podar International School,  
Hingoli.

**Subject: Request to issue the building Safety Certificate.**

**Reference:** - 1. Your letter dated 23/03/2022

2. As per the letter of Sub divisional engineer PWD Hingoli. Dated on 28/06/2022 letter No outward no / Ta/Shah/ 942

As per the referred letter it has been informed that Podar International School Survey No 5 plot no. 70 Jawala Palsi Road Siddhartha Nagar Hingoli requisition letter for issuing building safety certificate reference no 1 has been received in our office.

Sub divisional officer PWD Hingoli has physically inspected the school building and submitted the report to this office as per the reference letter. As per the report the building is in good condition at present and safe in all the aspects of the building safety rules.

For your information



-sd-

Executive Engineer

Public works department

Hingoli

Copy to – Sub divisional Engineer Public works department Sub divisional office Hingoli for further information



**SIGNED BEFORE ME**

*(Signature)*  
Vitthalrao P. Gayakwad  
Notary Government of India  
HINGOLI



महाराष्ट्र शासन  
सार्वजनिक बांधकाम विभाग हिंगोली

E-mail  
hingoli.ee@mahapwd.gov.in



कार्यालय  
कार्यकारी अभियंता,  
सा.बां.विभाग,हिंगोली.

जा.क्र.आरेखक/ 2780

दिनांक 07 JUL 2022

✓ प्रति,  
प्राचार्य,  
पोदार इंटरनॅशनल स्कुल,  
हिंगोली

**विषय:- Request to issue the building Safety Certificate**


संदर्भ :- 1.आपले पत्र दिनांक 23 / 03 /2022

2. उपविभागीय अभियंता सा.बां.हिंगोली.यांचे पत्र जा.क्र./ताशा/942  
दिनांक. 28.06.2022

उपरोक्त विषयी संदर्भीय पत्राच्या अनुषंगाने कळविण्यात येते की, पोदार इंटरनॅशनल स्कुल, सर्व्ह नं.०५ प्लॉट नं ७० मधील जवळा पळशी रोड,सिध्दार्थ नगर,हिंगोली या इमारतीस इमारत सुरक्षा प्रमाणपत्र देणेस्तव संदर्भीय पत्र क्र.१अन्वये आपले पत्र या कार्यालयास प्राप्त आहे.

उपविभागीय अभियंता,सा.बां.उपविभाग,हिंगोली यांनी सदर इमारतीची प्रत्यक्ष पाहणी करुन अहवाल संदर्भीय पत्रान्वये या कार्यालयास सादर केलेला आहे, त्यानुसार सद्यस्थितीत इमारत सुस्थितीत असुन इमारत सुरक्षीततेच्या दृष्टीकोनातुन योग्य आहे.

करिता माहितीस्तव.

  
कार्यकारी अभियंता  
सार्वजनिक बांधकाम विभाग  
हिंगोली

प्रत. उप विभागीय अभियंता,सार्वजनिक बांधकाम उपविभाग,हिंगोली यांना माहितीस्तव.